

# InstaShiatsu+ Massage Chair MC-1000

## MC-1000 Air Bag Troubleshooting

### 1. Ensure hoses are properly connected:

- Check the underside of the chair to locate the hoses.
- Examine the connections to ensure they are securely fastened.
- Make sure there are no kinks or blockages in the hoses that could impede proper airflow.



**2. Remove the seat cushion to check the connections:**

- Locate the seat cushion attachment points on the chair.
- Carefully remove the seat cushion to access the connections underneath.
- Inspect the connections to ensure they are properly seated and tightened.



**3. Remove the back cover of the chair to check the main hose connection:**

- Use a #2 Phillips screwdriver to remove the screws holding the back cover in place.
- Gently lift off the back cover to access the internal components.
- Locate the main hose connection point on the compressor unit.
- Check that the main hose is securely connected to the compressor.
- If necessary, reseal the hose connection to ensure a proper fit.

Note: It is important to exercise caution when handling the chair's components. If you encounter any difficulties during the process or are unsure about any steps, it is recommended to seek assistance from an authorized maintenance professional or refer to the chair's user manual for further guidance.

By following these steps, you can effectively check and ensure the proper connection of the hoses in your chair, helping to maintain optimal functionality and performance.